



检测报告

(深测) 检测字 (2022) 第 SC221008001 号

本报告共 5 页

受检单位: 深圳市第二职业技术学校

采样日期: 2022 年 10 月 08 日

检测项目: 甲醛、苯、甲苯、二甲苯、TVOC

检测类别: 现场采样

深圳市深测检测技术有限公司
Shenzhen Shence Testing Co., Ltd.



本机构通讯资料 (Contact of the SCJ) :

检测机构: 深圳市深测检测技术有限公司

联系地址: 深圳市宝安区航城街道新力塘 8 号 5 楼

联系电话: 0755-82596689

投诉电话: 0755-86297569

网 址: www.shencejc.com

检测说明

Detection statement

1、本报告只适用于检测目的范围。

This report is only applicable to the purpose and scope of the test.

2、本报告对现场采样样品所检项目结果负责，由委托方提供的抽检环境代表性和真实性由委托方负责。

This report is responsible for the results of the items tested by the on-site sampling samples, and the representativeness and authenticity of the sampling environment provided by the client shall be borne by the client.

3、本报告涂改无效。

This report is invalid if altered.

4、本报告无本公司检验专用章、骑缝章无效。

This report is invalid without the company's special inspection seal and cross stitch seal.

5、未经本公司书面批准，不得部分复制本报告。

This report shall not be partially copied without the written approval of the SCJ-company.

6、本检测结果仅代表检测时委托方提供的工况条件下检测值。

This test result only represents the test value under the working conditions provided by the client during the test.

本机构通讯资料 (Contact of the SCJ) :

检测机构: 深圳市深测检测技术有限公司

联系地址: 深圳市宝安区航城街道新力塘 8 号 5 楼

联系电话: 0755-82596689

投诉电话: 0755-86297569

网 址: www.shencejc.com

深圳市深测检测技术有限公司检测报告

1、检测目的

监测室内环境的污染程度。

2、检测对象

学校

3、分析方法与分析仪器（见表 1）

4、检测结果(见检测结果)

表 1 检测项目分析方法和分析仪器

检测项目	评价标准及数据	检验方法	仪器名称及型号
甲醛	$\leq 0.10\text{mg}/\text{m}^3$ GB/T18883-2002	分光光度法 GB/T18204.2-2014 (检出下限为: $0.01\text{mg}/\text{m}^3$)	722N 分光光度计
苯	$\leq 0.11\text{mg}/\text{m}^3$ GB/T18883-2002	气相色谱法 HJ 583-2010 (检出下限为: $5.0 \times 10^{-4}\text{mg}/\text{m}^3$)	GC5890N 气相色谱仪
甲苯	$\leq 0.20\text{mg}/\text{m}^3$ GB/T18883-2002	气相色谱法 HJ 583-2010 (检出下限为: $5.0 \times 10^{-4}\text{mg}/\text{m}^3$)	GC5890N 气相色谱仪
二甲苯	$\leq 0.20\text{mg}/\text{m}^3$ GB/T18883-2002	气相色谱法 HJ 583-2010 (检出下限为: $5.0 \times 10^{-4}\text{mg}/\text{m}^3$)	GC5890N 气相色谱仪
TVOC	$\leq 0.60\text{mg}/\text{m}^3$ GB/T18883-2002	热解析/气相色谱法 GB/T18883-2002 附录 C	GC5890N 气相色谱仪

深圳市深测检测技术有限公司检测报告

检测结果

(深测)检测字(2022)第SC221008001号

项目名称		室内环境污染物		检测项目 (室内空气)		甲醛、苯、甲苯、二甲苯、TVOC	
采样日期		2022 年 10 月 08 日		分析日期		2022 年 10 月 08 日-2022 年 10 月 10 日	
结果日期		2022 年 10 月 10 日		分析（采样）人员		邹中越、徐远明	
采样地址		深圳市光明区光明街道光侨大道 3409 号					
环境采样条件		温度 28.8℃、大气压 101.0Kpa 现场封闭 12 小时、测点位置由委托方提供					
样品 编号	采样点位	测试项目及分析结果					
		甲醛 mg/m ³	苯 mg/m ³	甲苯 mg/m ³	二甲苯 mg/m ³	TVOC mg/m ³	
001	心理咨询室 1 号房	0.041（合格）	0.0253（合格）	0.0200（合格）	0.0343（合格）	0.194（合格）	
002	心理咨询室 2 号房	0.028（合格）	0.0145（合格）	0.0144（合格）	0.0267（合格）	0.177（合格）	
003	心理咨询室 3 号房	0.028（合格）	0.0256（合格）	0.0194（合格）	0.0360（合格）	0.218（合格）	
004	心理咨询室 4 号房	0.025（合格）	0.0241（合格）	0.0203（合格）	0.0331（合格）	0.219（合格）	
005	心理咨询室 5 号房	0.037（合格）	0.0301（合格）	0.0191（合格）	0.0352（合格）	0.226（合格）	
006	电子商务实训室	0.030（合格）	0.0149（合格）	0.0183（合格）	0.0348（合格）	0.203（合格）	
检测结论		各检测点指标均符合《室内空气质量标准》GB/T18883-2002 的限值要求。					

编辑: 梁文静

审核: 梁文静



日期: 2022年10月10日

附采样图片:

 心理咨询室1号房 时 间: 2022.10.08 09:48 地 点: 深圳市·深圳市第二职业技术学 校 经纬度: 22.780150°N,113.941614°E 今日水印 相机	 心理咨询室2号房 时 间: 2022.10.08 09:48 地 点: 深圳市·深圳市第二职业技术学 校 经纬度: 22.780150°N,113.941614°E 今日水印 相机	 心理咨询室3号房 时 间: 2022.10.08 09:48 地 点: 深圳市·深圳市第二职业技术学 校 经纬度: 22.780150°N,113.941614°E 今日水印 相机
心理咨询室 1 号房	心理咨询室 2 号房	心理咨询室 3 号房
 心理咨询室4号房 时 间: 2022.10.08 09:49 地 点: 深圳市·深圳市第二职业技术学 校 经纬度: 22.779822°N,113.941718°E 今日水印 相机	 心理咨询室5号房 时 间: 2022.10.08 09:49 地 点: 深圳市·深圳市第二职业技术学 校 经纬度: 22.779822°N,113.941727°E 今日水印 相机	 电子商务实训室 时 间: 2022.10.08 10:04 地 点: 深圳市·深圳市第二职业技术学 校 经纬度: 22.780297°N,113.941559°E 今日水印 相机
心理咨询室 4 号房	心理咨询室 5 号房	电子商务实训室

-----本报告结束-----